## Message Text

UNCLASSIFIED

PAGE 01 STATE 170675

70

ORIGIN SSM-05

INFO OCT-01 NEA-10 ISO-00 OC-06 CCO-00 /022 R

DRAFTED BY SSM/PE:JWALLEN:MA APPROVED BY SSM:CLSTILES SSM/P:DQLAYNE A/OC/NEA:RCRIBERA

----- 084004

P R 092125Z JUL 76 FM SECSTATE WASHDC TO USMISSION SINAI PRIORITY INFO AMCONSUL KARACHI

**UNCLAS STATE 170675** 

SSM/SFM FOR CEO FRENCH

E.O,1652: N/A

TAGS: ACOM, PK

SUBJECT: USG COMMUNICATIONS -- TELREX ANTENNA

REF: SINAI 1259

- 1. THE PROBLEM WITH THE TELREX ANTENNA AND BALUN IS BEING ANALYZED. PROBLEM WILL BE DISCUSSED WITH TELREX WHEN EMPLOYEES RETURN FROM VACATION ON 13 JULY. PROBLEM ANALYSIS AND RECOMMENDED SOLUTION WILL BE PROVIDED BY 16 JULY.
- 2. INITIAL LOOK AT PROBLEM INDICATES POSSIBILITY OF CONDUCTIVE PATHS ON ANTENNA WHICH RESULT FROM COMBINATION OF DUST AND CONDENSATE WHICH MAY BEGIN TO FORM ON ANTENNA AFTER SUNDOWN. DAY AND NIGHT CONDUCTIVITY MEASUREMENTS ON FEED LINES OF ANTENNA WITH BALUN DISCONNECTED SHOULD PROVIDE DATA ON CONDUCTIVITY CHANGES. YOUR SUGGESTION THAT BALUN IS INADEQUATE IS ALSO POSSIBILITY. THIS WILL BE DISCUSSED WITH TELREX ON 13 JULY.

UNCLASSIFIED

UNCLASSIFIED

PAGE 02 STATE 170675

3. REQUEST YOU PROVIDE ANY ADDITIONAL INFORMATION WHICH

YOU MAY HAVE THAT WOULD HELP TO ANALYZE PROBLEM. SPEC-	
IFICALLY REQUEST DUTY CYCLE AND POWER LEVELS UNDER WHICH	ł
EACH BALUN FAILED. KISSINGER	

UNCLASSIFIED

NNN

## Message Attributes

Automatic Decaptioning: X Capture Date: 01 JAN 1994 Channel Indicators: n/a

**Current Classification: UNCLASSIFIED** 

Concepts: n/a Control Number: n/a Copy: SINGLE Draft Date: 09 JUL 1976 Decaption Date: 01 JAN 1960 Decaption Note: Disposition Action: n/a

Disposition Action: n/a
Disposition Approved on Date:
Disposition Authority: n/a
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 JAN 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1976STATE

Document Number: 1976STATE170675
Document Source: CORE
Document Unique ID: 00
Drafter: JWALLEN:MA Enclosure: n/a Executive Order: N/A Errors: N/A

Film Number: D760265-1062

From: STATE

Handling Restrictions: n/a

Image Path:

Legacy Key: link1976/newtext/t19760772/aaaaclkc.tel

Line Count: 64

Locator: TEXT ON-LINE, ON MICROFILM Office: ORIGIN SSM Original Classification: UNCLASSIFIED Original Handling Restrictions: n/a Original Previous Classification: n/a Original Previous Handling Restrictions: n/a

Page Count: 2

Previous Channel Indicators: Previous Classification: n/a Previous Handling Restrictions: n/a Reference: 76 SINAI 1259 Review Action: RELEASED, APPROVED Review Authority: morefirh

Review Comment: n/a Review Content Flags: Review Date: 09 MAR 2001

**Review Event:** 

Review Exemptions: n/a
Review History: RELEASED <09-Mar-2001 by daviscw>; APPROVED <29-Mar-2001 by morefirh>

**Review Markings:** 

Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 04 MÁY 2006

**Review Media Identifier:** Review Referrals: n/a Review Release Date: n/a Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

Secure: OPEN Status: NATIVE

Subject: USG COMMUNICATIONS -- TELREX ANTENNA TAGS: ACOM, PK

To: SINAI

Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 04 MAY 2006